

The Power to Protect Your World

Select the right 3M™ Respirator

	FFP1	FFP2	FFP3	Welding	Gas/Vapour
Work generating respirable crystalline silica (RCS) e.g.			●		
Cutting, grinding and drilling stone and concrete			●		
Scabbling			●		
Work with contaminated soil e.g.					● 4279
Earth moving					● 4279
Piling					● 4279
Underpinning					● 4279
Wood dust		●	●		
Low level dusts (not RCS)	●	●	●		
Plastering	●	●	●		
Welding				●	
Metal cutting				●	
Loft insulation			●		
Certain non-licensed asbestos work			●		
Roof felting					● 4251-4279
Solvent based timber treatments					● 4251-4279
Adhesives/sealants					● 4251-4279
Brick treatments					● 4251-4279
Painting (not 2-pack)					● 4251-4279

*This guide is only an outline. It is designed to help focus on the most appropriate respirators in the 3M range for particular applications. It should not be used as the only means of selecting a respirator.



3M Safety Solutions – OH&ESD
3M United Kingdom plc
 3M Centre,
 Cain Road,
 Bracknell
 Berkshire RG12 8HT
 Tel: 0870 60 800 60
www.3M.co.uk/construction

3M Ireland
 The Iveagh Building
 The Park
 Carrickmines
 Dublin 18
 Tel: 1800 320 500
www.3M.co.uk/construction

14705

